## Form Approved Dec. 1973 Budget Bureau No. 42-R1424 UNITED STATES 5. LEASE DEPARTMENT OF THE INTERIOR SF-077056 **GEOLOGICAL SURVEY** 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS 7. UNIT AGREEMENT NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.) 8. FARM OR LEASE NAME 1. oil gas Cozzens X well weil other 9. WELL NO. 2. NAME OF OPERATOR Southland Royalty Company 10. FIELD OR WILDCAT NAME 3. ADDRESS OF OPERATOR <u>Basin Dakota</u> P.O. Drawer 570, Farmington, NM 87401 11. SEC., T., R., M., OR BLK. AND SURVEY OR 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 AREA Section 18, T29N, R11W AT SURFACE: 1540' FSL & 1655' FEL 12. COUNTY OR PARISH 13. STATE AT TOP PROD. INTERVAL: San Juan New Mexico AT TOTAL DEPTH: 14. API NO. 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA 15. FLEVATIONS (SHOW DF, KDB, AND WD) SUBSEQUENT AE REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT OCT 12 1982 SHOOT OR ACIDIZE U. S. GEOLOGICAL SURVEY on Form 9-330.) FARMUNGTON N. M. REPAIR WELL (NOTE: Report results of multiple completion or zone PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON\* Re-Seeding (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 9-01-82 "Re-seeding has been completed as per stipulation."

Subsurface Safety Valve: Manu. and Type \_ Set @ \_ 18. I hereby certify that the foregoing is true and correct SIGNED DATE <u>October</u> 7, 1982 es TITLE Secretary (This space for Federal or State office use) APPROVED BY \_ TITLE \_ CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

'See Instructions on Reverse Side

OCT 14 1982



\_Elev.\_<u>5613\_GL\_\_Spd.</u>.2-7-81\_ Csg.Perf. Prod. Stim. BO/D \_MCF/D After\_ \_PSI After\_\_\_ Hrs. SICP. ..Days GOR TOPS NITD Well Log TEST DATA Kirtland C-103 Plat Schd. PC Q PW Ref.No. Fruitland C-104 Electric Log Pictured Cliffs C-122 Cliff House Ditr Dfa Menefee Datr Dac Point Lookout Mancos Gallup Sanostee Greenhorn Dakota Morrison Entrada

3<del>0</del>-045-24127 12-2<del>0</del>-79

Gal<sub>Co.</sub> SJ<sub>s</sub> 18 , 29N <sub>R</sub> 11W <sub>U</sub>J <sub>Oper.</sub> Southland Royalty Co <sub>Lee.</sub> Cozzens

160

<u>№</u>. 6E