## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

| Form 9–331<br>Dec. 1973  | Form Approved.<br>Budget Bureau No. 42-R1424   |
|--|--|
| UNITED STATES DEPARTMENT OF THE INTERIOR   | <b>5.</b> LEASE SF-080245  |
| GEOLOGICAL SURVEY  | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |
| SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different  | 7. UNIT AGREEMENT NAME   |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)   | 8. FARM OR LEASE NAME  |
| 1. oil gas XX other  | Hamner   |
| 2. NAME OF OPERATOR  | 9. WELL NO. 1997 - 1997 |
| Tenneco Oil Company  | 10. FIELD OR WILDCAT NAME  |
| 3. ADDRESS OF OPERATOR   | Dakota/Mesa Verde  |
| 720 S. Colo. Blvd., Denver, CO 80222   | 11. SEC., T., R., M., OR BLK. AND SURVEY OF  |
| 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17   | AREA STATE OF THE  |
| below.) 825'FNL, 1660'FWL, Unit C<br>AT SURFACE:   | Sec. 28; T29N; R9W   |
| AT TOP PROD. INTERVAL:   | 12. COUNTY OR PARKISH 13. STATE San Juan New Mexico  |
| AT TOTAL DEPTH:  | 14. API NO.  |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,  |  |
| REPORT, OR OTHER DATA  | 15. ELEVATIONS (SHOW DF, KDB, AND WD   |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:   | 5721'GR = 5721   |
| TEST WATER SHUT-OFF  | (QIII)   |
| SHOOT OR ACIDIZE   | 1 00 1   |
| REPAIR WELL   PULL OR ALTER CASING   T   | (NOTE: Report results of moviple completies or zoo   |
| MULTIPLE COMPLETE  | change of Fig. 3030.)  |
| CHANGE ZONES   | port Juliconst.  |
| ABANDON* (other) Plug and Sidetrack Production casing Rep  | oort Junconst.   |
|  |  |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent | rectionally drilled give rubeurfeed beefings and   |
| 4/17/80  |  |
| After several unsuccessful attempts to retriev   | ve fish, elected to plug and   |
| sidetrack. TIH openended and tagged top of fi  | sh @ 4890. Spotted 75 sxs of   |
| CL-B cmt. w/15% 20/40 mesh sand and 3/4% CFR-2   | 2. WOC. Tagged plug @ 4800'.   |
| (Cmt plug: 4800-90) Drilled cmt to 4821' and b   | pegan sidetrack. Wiped dogleg  |
| and resumed drilling down sidetracked hole. R  | Reached TD $\overline{of}$ 6707 on $4/28/80$ .   |
| Ran and set 64 jts of 4 1/2", 10.5# 11.6# csg  | w/liner assembly 0 6/14/3  |
| TOL: 4646. Cmt. w/170 sxs 50/50 Pozmix. Tailed Released rig 4/30/80. WOCU.   | W/15U SXS CLEB. Circ to 4646.  |
| Nereased 119 47 307 00. Noto.  |  |
|  |  |
|  | ရုံးရှိသို့ သည်။ ရုံရှိသည်။<br>မွေးများများသည် ရုံရှိသည်။  |
|  |  |
| Subsurface Safety Valve: Manu. and Type  |  |
| 18. I hereby certify that the foregoing is true and correct  |  |
| SHONED WILLY MILLE Admin. Super  | VISOBATE 5/2/80  |
| (This space for Federal or State office  | ce use)  |

Subsurface Safety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct SIGNED <u>Admin. Sı</u> (This space for Federal or Stat APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY: č. -

MAY 28 1980

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

| _  | 4 E40E       |
|----|--------------|
| Э. | SF-080245    |
|    | SE=080245    |
|    | JI - UUULTJ. |

| 6. | IF INDIAN, | ALLOTTEE | OR TRIBE | NAME |
|----|------------|----------|----------|------|

| SUNDRY | NOTICES | AND | REPORTS | ON | WELLS |
|--------|---------|-----|---------|----|-------|
|--------|---------|-----|---------|----|-------|

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)

1. oil gas well other

2. NAME OF OPERATOR
Tenneco 0il Company

**3. ADDRESS OF OPERATOR**720 S. Colo. Blvd., Denver, CO 80222

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 825'FNL, 1660'FWL, Unit C
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

| 8. | FARM | OR LEASE | NAME |
|----|------|----------|------|
|    |      |          |      |

7. UNIT AGREEMENT NAME

Hamner :

**9. WELL NO.** 2A

10. FIELD OR WILDCAT NAME
Dakota/Mesa Verde

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 28; T29N; R9W

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

14. API NO.

(NOTE: Report res

change of

15. ELEVATIONS (SHOW DF, KDB, AND WD) 5721 GR

CHANGE ZONES

ABANDON\*
(other)

Plug and Sidetrack, Production Casing Report

SUBSEQUENT REPORT OF:

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4/17/80

REQUEST FOR APPROVAL TO:
TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

6 1/4" hole drilled to a total depth of 4890. Attempt to set BP inside of 7" casing. Bridge plug parted in hole. Unable to recover fish after several attempts. Bridge plug pushed to bottom 0 4890. Fish left in hole 4890-4888. TIH open ended to top of fish. Spot 75 sx plug. 4888 to 4800. WOC. TIH & tag top of cement 0 4800 dressed off cement plug to 4821. TIH w/side tracking tools & sidetrack around fish 0 4839. Resume drilling to a total depth of 6707'

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED TITLE Admin. Supervisor DATE 5/15/80

(This space for Federal or State office use)

APPROVED BY

TITLE DATE

?' \* e \_

ACCEPTED FOR RECORD

MAY 28 1980

FARMUIG ON CISTRICT

\*See Instructions on Reverse Side