Form Approved.

UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE

PULL OR ALTER CASING MULTIPLE COMPLETE **CHANGE ZONES** ABANDON*

REPAIR WELL

Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES DEPARTMENT OF THE INTERIOR	5. LEASE SF-078580A
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME Moore
1. oil gas de other	9. WELL NO. 6E
2. NAME OF OPERATOR Tenneco Oil Company 3. ADDRESS OF OPERATOR 720 S. Colo. Blvd., Denver, CO 80222 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1750'FSL 1750'FEL AT SURFACE: AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	10. FIELD OR WILDCAT NAME Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5; T30N; R8W 12. COUNTY OR PARISH San Juan New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 6265 GR

(NOTE: Report resu

change o

(other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and including estimated date of starting any proposed work. If well is directionally drilled, give substanced and true vertical depths for all markers and zones pertinent to this work.)*

7/4-7/5/80

Spudded 13 3/4"hole 7/4/80. Ran 7 jts 9 5/8", 36# csg set @ 289 KB. Cmt w/200 sx CL-B w/2% CACL2. Circ 10 bbls cmt. WOC.

SUBSEQUENT REPORT OF:

ACCEPTED FOR RECORD

OCT 9 1980

FARMINGTON DISTRICT RY. Set @ ___ Subsurface Safety Valve: Manu. and Type certify that the foregoing is true and correct ASST. Div. Admin. Manager 9/10/80 TITLE SIGNED (This space for Federal or State office use) DATE APPROVED BY CONDITIONS OF APPROVAL, IF ANY:

See Instructions on Reverse Side