## UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

ABANDON\*Casing Report

Form 9-331 Dec. 1973	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	SF-076958
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELL  (Do not use this form for proposals to drill or to deepen or plug back to a diff	ferent
reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas XX other	Hare
	9. WELL NO.
2. NAME OF OPERATOR	15-M 10. FIELD OR WILDCAT NAME
Southland Royalty Company	Basin Dakota/Blanco Mesa Verde
3. ADDRESS OF OPERATOR	11. SEC., T., R., M., OR BLK. AND SURVEY OR
P.O. Drawer 570, Farmington, New Mexico  4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space	
below.)	Section 3, T29N, R10W
AT SURFACE: 930' FSL & 1770' FEL	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL:	San Juan New Mexico
AT TOTAL DEPTH:	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOT	TICE,
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	5862' GR
TEST WATER SHUT-OFF	
FRACTURE TREAT	
SUCOT OR ACIDIZE	(NOTE: Report results of multiple confortion on zone change on Form 9–330.0/L
REPAIR WELL RECE	(NOTE: Report results of multiple control tion on zone
PULL OR ALTER CASING	
CHANGE ZONES	DIST. 3
ARANDON*	( -101. 3

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*
- Ran 166 joints (6924') of 5-1/2", 15.5#, K-55 casing set at 6932'. 9/24/80 DV tools set at 4827' and 2410'.

Cemented as follows: 9/25/80

> 1st Stage cemented with 124 sacks of 50/50 Poz with 1/4# gel flake per sack and 6% gel followed by 50 sacks of Class "B" with 2% CaCl2. Plug down at 9:00 A.M. 9-25-80.

> 2nd Stage cemented with 163 sacks of 50/50 Poz with 1/4# gel flake per sack and 6% gel. Plug down at 2:00 P.M. 9-25-80.

> 3rd Stage cemented with 296 sacks of 50/50 Poz with 1/4# gel flake per sack and 6% gel. Plug down at 5:45 P.M. 9-25-80.

Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true and correct	•
SIGNED AN TITLE Dist. Prod. Mgr. DATE	September 26, 1980
(This space for Federal or State office use)	
APPROVED BY TITLE DATE	E