UNITED STATES DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

Dec. 1973	Budget Bureau No. 42–R1424			
UNITED STATES	5. LEASE			
DEPARTMENT OF THE INTERIOR	SF065557			
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME			
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME			
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME			
1. oil gas vv	Federal PRI			
well well other	9. WELL NO.			
2. NAME OF OPERATOR	1-E			
Southland Royalty Company	10. FIELD OR WILDCAT NAME			
3. ADDRESS OF OPERATOR	Basin_Dakota			
P. O. Drawer 570, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY O			
helow.)	Section 11, T29N, R12W			
AT SURFACE: 1750' FNL & 1045' FEL	12. COUNTY OR PARISH 13. STATE			
AT TOP PROD. INTERVAL:	San Juan New Mexico			
AT TOTAL DEPTH:	14. API NO.			
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,				

1.	oil well		gas well	XX	othe	er				
2.	NAM	E OF	OPERA	TOR						
		and RESS (ar	ı y			
Ρ.	_0.	Dra	wer	570,	Fari	nir	igton	N.M.	87401	
4.	LOCA	TION	OF WE	LL (R	EPORT	LO	CATION	CLEARLY.	See space	17
	belov AT S	v.) URFAC	E: 17	750'	FNL	ક	1045'	FEL		

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Spud and Casing Report

SUBSEQUENT REPORT OF:

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

15. ELEVATIONS (SHOW DF, KDB, AND WD)

5767' GR

(NOTE: Report results of multip change on Form 9-33

Spudded 12-1/4" surface hole at 5:00 P.M. 10-09-80 and drilled to 10/09/80 a Total Depth of 230'. Ran 5 joints (215') of 8-5/8", 24#, K-55 casing set at 227'. Cemented with 140 sacks of Class "B" with 1/4# gel flake per sack and 3% CaCl2. Plug down at 2:45 A.M. 10-10-80. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Typ		Set @ Ft.
18. I hereby certify that the foregoing is	true and correct TITLE <u>Dist. Prod. Mgr</u>	. DATE October 10, 1980
RECEIVED FOR RECEIVE	(This space for Federal or State office use)
APPROVED BY CONDITIONS OF LAPPROVAL, IF LANY:	TITLE	DATE
CONDITIONS OF CAPPROVAL, IF CANY	MMOCO	•