

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-2447	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name Gallegos Canyon Unit
2. Name of Operator Energy Reserves Group, Inc.		8. Farm or Lease Name
3. Address of Operator P. O. Box 3280, Casper, Wy. 82602		9. Well No. 324
4. Location of Well UNIT LETTER <u>G</u> , <u>1590</u> FEET FROM THE <u>North</u> LINE AND <u>1450</u> FEET FROM THE <u>East</u> LINE, SECTION <u>32</u> TOWNSHIP <u>29N</u> RANGE <u>12W</u> NMPM.		10. Field and Pool, or Wildcat West Kutz Pictured Cliffs
15. Elevation (Show whether DF, RT, GR, etc.) GL 5472' KB 5474'		12. County San Juan

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <u>Recement csg.</u> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6-3-81 The 7" surface casing - 4 1/2" production casing annulus was squeezed with 50 sx. of 50-50 Pozmix with 2% gel & 2% CC. Then a temperature survey was run, and bottom of the cement was found to be at 225'.



18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P. Wagner TITLE Production Engineer -RMD DATE 6-23-81

APPROVED BY Original Signed by FRANK T. CHAVEZ TITLE SUPERVISOR DISTRICT # 3 DATE JUN 26 1981

CONDITIONS OF APPROVAL, IF ANY: