

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other
-
2. NAME OF OPERATOR
Southland Royalty Company
-
3. ADDRESS OF OPERATOR
P.O. Drawer 570, Farmington, New Mexico 87401
-
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 830' FSL & 960' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
-
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | | |
|---|-------------------------|
| 5. LEASE
SF-076958 | |
| 6. IF INDIAN, ALLOTTEE OR TRIBE NAME | |
| 7. UNIT AGREEMENT NAME | |
| 8. FARM OR LEASE NAME
Hare | |
| 9. WELL NO.
23 | |
| 10. FIELD OR WILDCAT NAME
Undesignated Fruitland | |
| 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 3, T29N, R10W | |
| 12. COUNTY OR PARISH
San Juan | 13. STATE
New Mexico |
| 14. API NO. | |
| 15. ELEVATIONS (SHOW DF, KDB, AND WD)
5838' GR | |

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other) Spud & Casing	<input type="checkbox"/>

□ □ □ □ □ □ □ □

RECEIVED

JAN 18 1952

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1/14/82 Spudded 12-1/4" surface hole at 5:00 P.M. 1-14-82 and drilled to total depth of 185'. Ran 4 joints (171') of 8-5/8", 24#, K-55 casing set at 182'. Cemented with 155 sacks of Class "B" with 1/4# flocele per sack and 3% CaCl₂. Plug down at 9:45 P.M. 1-14-82. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

- 18. I hereby certify that the foregoing is true and correct**

SIGNED Catherine Dwyer TITLE Drilling Clerk DATE January 15, 1982

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

NMOCC

***See Instructions on Reverse Side**

ACCEPTED FOR RECORD

JAN 20 1982

FARMINGTON DISTRICT

RV