

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐
2. NAME OF OPERATOR
Southland Royalty Company
3. ADDRESS OF OPERATOR
P.O. Drawer 570, Farmington, N.M. 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1530' FNL & 1585' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

☐
☐
☐
☐
☐
☐
☐
☐

(other) Spud and Casing Report ☒

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)
DEC 30 1980

U. S. GEOLOGICAL SURVEY
FARMINGTON, N. M.

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/26/80 Spudded 12-1/4" surface hole at 6:30 P.M. 12-26-80 and drilled to a Total Depth of 180'. Ran 4 joints (161') of 8-5/8", 24#, H-40 casing set at 173'. Cemented with 150 sacks of Class "B" with 1/4# flocele per sack and 3% CaCl₂. Plug down at 12:01 A.M. 12-27-80. Cement circulated to surface.

Subsurface Safety Valve: Manu. and Type _____

Set @ OIL CON. COM.
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED Ethel Greyson TITLE Drilling Clerk DATE 12-29-80

ACCEPTED FOR RECORD (space for Federal or State office use)

APPROVED BY JAN 08 1981 TITLE _____ DATE _____
CONDITIONS OF APPROVAL: _____

BY BW FARMINGTON DISTRICT

*See Instructions on Reverse Side