

District I

P.O. Box 1980, Hobbs, NM

District II

P.O. Drawer, Artesia, NM 88211

District III

1000 Rio Brazos Rd. Aztec, NM 87410

State Of New Mexico

Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 1 COPY TO

APPROPRIATE

DISTRICT OFFICE

AND 1 COPY TO

SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: Conoco Inc.Telephone: 505-324-5813Address: 3315 Bloomfield Hwy Farmington NM 87401Facility Or: HAMNER 2E

Well Name

Location: Unit or Qtr/Qtr Sec K Sec 28 T 29N/R 09W County SAN JUANPit Type: Separator Dehydrator Other TANK DRAIN PIT.Land Type: BLM ☒ State Fee OtherPit Location:
(Attach diagram)Pit dimension: length 6' width 4' depth 1'Reference: wellhead ☒ otherFootage from reference: 118'Direction from reference: 150° Degrees East of North
West of South ☒

Depth To Ground Water:

(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet (20 points)

50 feet to 9 feet (10 points)

Greater than 100 feet (0 points)

Total 0

Wellhead Protection Area:

(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)

No (0 points)

Total 0


Distance To Surface Water:

(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points) (20 points)

200 feet to 1000 feet (10 points) (10 points)

Greater than 1000 feet (0 points) (0 points)

Total 0RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: <u>8-13-99</u>		Date Completed: <u>8-18-99</u>	
Remediation Method: <u>Excavation:</u>		Approx. cubic yards <u> </u>	
(Check all appropriate sections)			
<u>Landfarm</u>		<u>Insitu Bioremediation</u>	
<u>Other</u>			
Remediation Location: <u>Onsite</u>		<u>Offsite</u>	
(ie. landfarmed onsite, name and location of offsite facility)			
General Description Of Remedial Action: <u>Sample taken, Till Bottom of Pit 1' IN, Back Fill</u>			
<u>With clean soil.</u>			
Ground Water Encountered: No ☒ Yes ☐ Depth <u> </u>			
Final Pit:		Sample location <u>CENTER OF PIT</u>	
Closure Sampling:			
(if multiple samples attach sample results and diagram of sample locations and depths)		Sample depth <u>4'</u>	
		Sample date <u>8-11-99</u> Sample time <u>1315</u>	
Sample Results			
Benzene (ppm)		<u> </u>	
Total BTEX (ppm)		<u> </u>	
Field headspace (ppm)		<u>16</u>	
TPH		<u>1.0</u>	
Ground Water Sample: Yes ☐ No ☒ (If yes, attach sample results)			
I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIEF			
DATE <u>11-30-99</u>		PRINTED NAME <u>Judson Valdez</u>	
SIGNATURE <u>Judson Valdez</u>		AND TITLE <u>P.L.</u>	

ENVIROTECH LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco Inc.	Project #:	707003-075
Sample ID:	TDP - Grab	Date Reported:	08-17-99
Laboratory Number:	F902	Date Sampled:	08-11-99
Chain of Custody No:	7131	Date Received:	08-13-99
Sample Matrix:	Soil	Date Extracted:	08-16-99
Preservative:	Cool	Date Analyzed:	08-16-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	1.0	0.1
Total Petroleum Hydrocarbons	1.0	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Hamner 2 E. OVM Reading 16.**


Analyst


Review

7131

ENVIROTECH INC.


5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

293.64
15.51
278.00

Lease Name: HAMNER #2E OK

Operator: LC Bob Williams Date: 8-11-99

Site Security
(Indicate North)



Lease Name: Hamner 2E

Federal/ Indian Lease No: SF 080245

CA No.: NA

Unit: K

Legal Description: Sect: 28 TP: 29N R: 9W

County: San Juan, NM

Load line valves :
Sealed during Production



Drain line valves :
Sealed during Production

Production Line valve:
Sealed during sales


This lease is subject to the site security plan for
San Juan Basin Operations. The plan is located at:
Conoco Inc.
3315 Bloomfield Hwy
Farmington, NM

8-11-99

Hamner ZE




DAP-
Time 1303 PPM 255
270° W
25-63' FWH
Hit Rock Bed 1' IN



BDP
Time 1309 PPM 303
214° S
32-80' FWH
Hit Rock Bed 2' IN



TDP 
Time 1308 PPM 9
150° S
47-118' FWH
1



SEP
Time 01359 PPM 318
102° E
37-93' FWH.
ST-Q1300