Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

| DEPARTMENT OF THE INTERIOR | SF-076958 |
|---|--|
| GEOLOGICAL SURVEY | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME |
| SUNDRY NOTICES AND REPORTS ON WELLS | 7. UNIT AGREEMENT NAME |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.) | 8. FARM OR LEASE NAME Hare |
| 1. oil gas K other | 9. WELL NO. 17-E 10. FIELD OR WILDCAT NAME |
| 2. NAME OF OPERATOR Southland Royalty Company | |
| 3. ADDRESS OF OPERATOR P.O. Drawer 570, Farmington, N.M. 87401 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1810' FNL & 1840' FWL AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: TEST WATER SHUT-OFF FRACTURE TREAT | Blanco Mesa Verde/Basin Dakota 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Section 15, T29N, R10W 12. COUNTY OR PARISH San Juan 13. STATE New Mexico 14. API NO. 15. ELEVATIONS (SHOW DF, KDB AND 5741' GR |
| SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) Spud and Casing Report 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is demeasured and true vertical depths for all markers and zones pertinents. | e all pertinent details, and give pertinent dates. |
| measured and true vertical depths for all markers and zones pertiner 2/22/81 Spudded 13-3/4" surface hole at 12:45 Total Depth of 225'. Ran 5 joints (20 casing set at 212'. Cemented with 140 3% CaCl2. Plug down at 6:45 P.M. 2-22 | A.M. 2-22-81 and drilled to a 0.25') of 10-3/4", 32.75#, H-40 sacks of Class "B" neat with |
| Subsurface Safety Valve: Manu. and Type | Set @ Ft. |
| | February 23, 1981 |
| (This space for Federal or State office use) | |

_____ TITLE

_____ DATE ___