

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other

2. NAME OF OPERATOR  
*SUPRON ENERGY CORPORATION*

3. ADDRESS OF OPERATOR  
*P.O. Box 808, Farmington, New Mexico 87401*

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: *1120 ft./S ; 825 ft./E line*  
AT TOP PROD. INTERVAL: *Same as above*  
AT TOTAL DEPTH: *Same as above*

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐  
(other) ☐

SUBSEQUENT REPORT OF:

☒  
☐  
☐  
☐  
☐  
☐  
☐  
☐  
☐

RECEIVED

MAR 2

U. S. GEOLOGICAL SURVEY  
FARMINGTON, N. M.

5. LEASE

*SF 047020 A*

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

*Congress*

9. WELL NO.

*5-E*

10. FIELD OR WILDCAT NAME

*Basin Dakota; Bloomfield Chacra Ext.*

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

*Sec. 34, T-29N, R-11W, N.M.P.M.*

12. COUNTY OR PARISH

*San Juan*

13. STATE

*New Mexico*

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

*6590 R.K.B.*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- Spudded 12 1/4" hole at 9:00 p.m. 3-21-81.*
- Drilled 12 1/4" surface hole to total depth of 296 ft. R.K.B.*
- Ran 6 joints of 8-5/8", 24.00# H-40 casing and set at 294 ft. R.K.B.*
- Cemented with 220 sacks of class "B" with 3% calcium chloride. Plug down at 6:15 a.m. 3-22-81. Cement circulated to the surface.*
- Waited on cement for 12 hours.*
- Pressure-tested casing to 600 P.S.I. for 30 minutes. Held OK.*

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *Kenneth E. Roddy* TITLE *Production Supt.* DATE *March 24, 1981*  
*Kenneth E. Roddy*

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 26 1981

\*See Instructions on Reverse Side

NM000

FARMINGTON DISTRICT  
BY *E. J. [Signature]*