## UNITED STATES DEPARTMENT OF THE INTERIOR GFOLOGICAL SURVEY

rm 9–331	Form Approved. Budget Bureau No. 42-R1424	
ec. 1973 UNITED STATES	5. LEASE	
DEPARTMENT OF THE INTERIOR	SF-080247	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME	
o not use this form for proposals to drill or to deepen or plug back to a different servoir. Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME	
l. oil gas ⊠ other	Florance  9. WELL NO. 117E  10. FIELD OR WILDCAT NAME Basin Dakota  11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA 35	
. NAME OF OPERATOR		
Tenneco Oil Company  B. ADDRESS OF OPERATOR		
P. O. Box 3249, Englewood, CO 80155  1. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17		
below.) AT SURFACE: 1780' FNL 990' FEL "H"	Section 25, T29N R9W  12. COUNTY OR PARISH 13. STATE	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	San Juan New Mexico	
5. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,		
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5665' qr.	
RACTURE TREAT HOOT OR ACIDIZE EPAIR WELL ULL OF COMPLETE  OULL OF COMPLETE  OULL OF COMPLETE  OULL OF COMPLETE	(NOTE: Report results of multiple completion or zone change on Form 9–330.)  The standard of t	
5/4/81 - RIH w/tbg. Seating nipple and pump ou but to PBTD w/N2 and foam. Ran tbg @ 6477'. R GR inside 2-3/8" tbg and log. Kicked well arou RDMOSU.	t plug. Tag sand @ 6565'. Clean emove BOP, install well head. Ra	
7/19/81 - MIRUSU.		
7/20/81 - Install BOP.		
Subsurface Safety Valve: Manu. and Type	Set @	
18. I hereby certify that the foregoing is true and correct	7 /07 /01	
SIGNED 1	nalyst DATE 7/27/81	
(This space for Federal or State	office use) DATE	

Subsurface Safety Valve: Manu. and Ty	pe	Set @
18. I hereby certify that the foregoing is		TE 7/27/81
70	(This space for Federal or State office use)	PATE
APPROVED BY	NMOCC;	22 1
		.Ja - 0 1931

\*See Instructions on Reverse Side

....TNGTON ... SMM bí\_