

District I
P.O. Box 1888, Hobbs, NM

District II
P.O. Drawer 60, Artesia, NM 88211

District III
1000 Rio Grande Rd, Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

OK
SUBMIT 1 COPY TO
APPROPRIATE
DISTRICT OFFICE
AND 1 COPY TO
SANTA FE OFFICE

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

Operator: CONOCO INC. Telephone: 505-324-5813

Address: 3315 Bloomfield HWY. FARMINGTON N.M. 87401

Facility Or: HELEN JACKSON 2E
Well Name

Location: Unit or qtr/qtr sec B sec 33 T29N R09W County SAN JUAN

Pit Type: separator ☐ Dehydrator ☐ other TANK Drain Pit

Land Type: BLM ☒, State ☐, Fee ☐, other ☐

Pit Location: Pit dimensions: length 3', width 3', depth 1'
(Attach diagram)


Reference: wellhead ☒, other ☐

Footage from reference: 128'

Direction from reference: 265° Degrees ☐ East ☐ North ☒ West ☐ South

Depth To Ground Water:
(Vertical distance from
contaminants to seasonal
high water elevation of
ground water)

Less than 50 feet (20 points)
50 feet to 99 feet (10 points)
Greater than 100 feet (0 points) 0



Wellhead Protection Area:
(Less than 200 feet from a private
domestic water source, or; less than
1000 feet from all other water sources)

Yes (20 points)
No (0 points) 0

Distance To Surface Water:
(Horizontal distance to perennial
lakes, ponds, rivers, streams, creeks,
irrigation canals and ditches)

Less than 200 feet (20 points)
200 feet to 1000 feet (10 points)
Greater than 1000 feet (0 points) 0

RANKING SCORE (TOTAL POINTS): 0

Date Remediation Started: Aug. 19, 1999 Date Completed: Aug. 19, 1999

Remediation Method: Excavation _____ Approx. cubic yards _____
(Check all appropriate sections) Landfarmed _____ Insitu Bioremediation _____
Other _____

Remediation Location: onsite ☒ offsite _____
(ie. landfarmed onsite,
name and location of
offsite facility)

General Description Of Remedial Action: SAMPLE TAKEN TO BOTTOM OF PIT 1' IN
BACK FILL CLEAN SOIL

Ground Water Encountered: No ☒ Yes _____ Depth _____

Final Pit:

sample location CENTER OF PIT

Closure Sampling:

(if multiple samples,
attach sample results
and diagram of sample
locations and depths)

sample depth 4'

sample date 8-17-99 sample time 1358

Sample Results

Benzene (ppm) _____

Total BTEX (ppm) _____

Field headspace (ppm) 0

TPH 582

Ground Water Sample: Yes _____ No ☒ (If yes, attach sample results)

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST
OF MY KNOWLEDGE AND BELIEF

DATE 12/13/99

SIGNATURE

John Valtz

PRINTED NAME

AND TITLE

Judson Valtz P.L.

ENVIROTECH. LABS

PRACTICAL SOLUTIONS FOR A BETTER TOMORROW

EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons


Client:	Conoco	Project #:	707003-080
Sample ID:	TDP - Grab	Date Reported:	08-24-99
Laboratory Number:	F947	Date Sampled:	08-17-99
Chain of Custody No:	7134	Date Received:	08-20-99
Sample Matrix:	Soil	Date Extracted:	08-23-99
Preservative:	Cool	Date Analyzed:	08-23-99
Condition:	Cool and Intact	Analysis Requested:	8015 TPH


Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	0.2	0.2
Diesel Range (C10 - C28)	582	0.1
Total Petroleum Hydrocarbons	582	0.2

ND - Parameter not detected at the stated detection limit.

References: Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846, USEPA, December 1996.

Comments: **Helen Jackson 2 E. OVM Reading 0.**
Hit Rock Bed 1' IN.


Analyst



Review

7134

ENVIROTECH INC.

5796 U.S. Highway 64
Farmington, New Mexico 87401
(505) 632-0615

Lease Name: HELEN JACKSON 2E Operator: LCR 66 William Date: 8-17-99
 Site Security
 (Indicate North)



Lease Name: Helen Jackson 2E
 Federal/ Indian Lease No: SF 077947
 CA No.: NA
 Unit: B
 Legal Description: Sect: 33 TP: 29N R: 4W
 County: San Juan, NM

Load line valves :
 Sealed during Production




Drain line valves :
 Sealed during Production

Production Line valve:
 Sealed during sales

This lease is subject to the site security plan for
 San Juan Basin Operations. The plan is located at:
 Conoco Inc.
 3315 Bloomfield Hwy
 Farmington, NM

Helen JACKSON 2E

8-17-99



TOP
265° W
128' FWH



Time - 1358
APM - 0
S.T. - 1400

SEP
222° W
123' FWH

Time - 1403
APM - 389
S.T. - 1405