UNITED STATES

DEDARTMENT OF THE INCOME	5. LEASE = 9 4		
DEPARTMENT OF THE INTERIOR	SF 076958		
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	=		
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME		
(Do not use this form for proposals to drill or to decpen or plug back to a differer reservoir. Use Form 9–331–C for such proposals.)	nt E		
	O. FARM OR LEASE NAME = = = = =		
1. oil gas	Albright		
well well do other	9. WELL NO.		
2. NAME OF OPERATOR	8-E		
Supron Energy Corporation	10. FIELD OR WILDCAT NAME		
3. ADDRESS OF OPERATOR	Basin Dakota - Blanco Mesaverde		
P.O. Box 808, Farmington, NM 87401	11. SEC., T., R., M., OR BLK. AND SURVEY OR		
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA		
below.)	Sec. 15, T29N, R10W, N.M.P.M.		
AT SURFACE: 790 ft./S; 1615 ft./E line	12. COUNTY OR PARISH 13. STATE		
AT TOP PROD. INTERVAL: Same as above	· · · · · · · · · · · · · · · · · · ·		
AT TOTAL DEPTH: Same as above	San Juan New Mexico		
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE	14. API NO.		
REPORT, OR OTHER DATA			
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF	5691 R.K.B.		
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF □ √7			
EPACTURE TREAT	· · ·		
SHOOT OR ACIDIZE	F Treatment Systems		
REPAIR WELL	(NOTE: Report results of multiple completion or zone change on Form 9–330.)		
PULL OR ALTER CASING	(NOTE: Report results of multiple completion or zone		
MULTIPLE COMPLETE			
CHANGE ZONES	# # # P		
ABANDON* U. S. GCOLOGICAL	SURVEY		
(other) FARMINGTON, N	V. M.		
	3 6 7 7 7 7		
 DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly sta including estimated date of starting any proposed work. If well is 	ite all pertinent details, and give pertinent dates,		
measured and true vertical depths for all markers and zones pertine	ent to this work.)*		
1. Spudded 13%" surface hole at 3:30 a.m. 4/3/	the state of the s		
2. Drilled 13%" surface hole to total depth of	F 224 Ft D V D		
3. Ran 8 joints of 8 5/8". 24.00#. K-55 casing	. 334 IC. R.K.B.		
5	and set at 334 ft. R.K.B.		
The second of Orang D William	3% Calcium Chioride. Plug down at		
9:00 p.m. 4/3/82. Cement circulated to sur	rface.		
5. Waited on cement for 12 hours.			
6. Pressure-tested casing to 1000 P.S.I. for 1	15 minutes. Held OK.		
	도 보다 하는 사람들은 사람들이 되었다. 그 사람들은 사람들이 다른 사람들이 다른 사람들이 되었다. 그 사람들이 다른 사람들이 되었다. 그 사람들이 되었다면 하는 사람들이 되었다면 보다 되었다면 보니 되었다면		
- .			
	မ ခုန္ညို ၌ ချေခုန္းမှ မ		
Subsurface Safety Valve: Manu, and Type	Tation Fa		

Subsurface Safety Valve: Manu. and Typ	oe		Set @	Ft.
18. I hereby certify that the foregoing is		- - ,		
SIGNED Kenneth E. Koldy Kenneth E. Roddy	TITLE <u>Production Supt.</u>	DATE April	5, 1982.	<u> </u>
	(This space for Federal or State office use)			5
APPROVED BY	TITLE	_ DATE) 12 1	5 1 T

ASCEPTED FOR RECORD

*See Instructions on Reverse Side

FF 03 1982

FARMINGTON DISTRICT

BY_