

Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department Form C-103 Revised 1-1-89

DISTRICT | P.O. Box 1980, Hobbs, NM 88240

WELL API NO.

	RVATION DIVISION	30-045-25146
DISTRICT II P.O. Box DD, Artesia, NM 88210	0 Pacheco St.	5. INDICATE TYPE OF LEASE
DISTRICT III Santa	Fe, NM 87505	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410		6. STATE OIL & GAS LEASE NO.
SUNDRY NOTICES AND REPORTS	ONWELLO	
UU NUI USE THIS FORM FOR PROPOSALS TO DOLL OF TO	` D	7 IFASE NAME OR UNIT
THE PROPERTY OF THE PROPERTY O	ION FOR PERMITS	7. LEASE NAME OR UNIT AGREEMENT NAME
I. TYPE OF WELL:	ALID ECET TO	State B Com
OIL WELL GAS WELL OTHER	In(9112
2. NAME OF OPERATOR	UU JUN 3 U 1999	8. WELL NO.
CONOCO INC. 3. ADDRESS OF OPERATOR		1E
10 DESTA DR., SUITE 100W, MIDLAND, TX 7970	ONL CONS DEED	9. POOL NAME OR WILDCAT
4. WELL LOCATION	05-4500 [គ្រាត្រា ្រ	Basin Dakota
Unit Letter "E": 1800' Feet From The NORTH Line ar	nd 1180' Foot From The MISST	
Section 16 Township 29N Range 10W NMPM Sai	Tion reel from the <u>VVEST</u>	Line
LEEVATION (Show whether DF, RKB, RT, GR, etc.) 5772' GL	
11. Check Appropriate Box to I	ndicate Nature of Notice, Report, or C	Other Data
NOTICE OF INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JO	
OTHER:	— !	
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all SEE RULE 1103.	OTHER: Clean Fill/Chang	ge Packer
SEE RULE 1103.	perunent dates, and give pertinent dates, in	cluding estimated date of starting any proposed work)
6/18/99 MIRU. Spot all equipment. Check wellhead pressur	es Cea - 560 poi Tha FGO: F	Manual L
6/18/99 MIRU. Spot all equipment. Check wellhead pressures. Csg - 560 psi. Tbg - 560 psi. Blow down casing, and kill tbg with 2% KCL water. NDWH & NUBOP. Released Hallib R-4 packer. POOH with 2 3/8" tubing with Hallib R-4 packer. Lost rubbers from packer, tore up. Tally all tubing. Tagged fill @ 6618'.		
Tally all tubing. Tagged fill @ 6618'.	5	passer, tore up.
6/21/99 Check well pressures. CSG - 560 psi. RIH with 2	3/8" tubing with Hallib The Role	r Torrad SII O cocci vi
6/21/99 Check well pressures. CSG - 560 psi. RIH with 2 3/8" tubing with Hallib Tbg Baler. Tagged fill @ 6628'. Worked baler and cleaned fill to 6706'. Baler quit working. POOH with 2 3/8" tubing with Hallib Tbg Baler. RIH with replacement tubing baler and tagged fill @ 6690'. Cleaned fill to PBTD @ 6742'. POOH with 2 3/8" tubing and Hallib Tbg Baler.		
6690'. Cleaned fill to PBTD @ 6742'. POOH with 2 3/8" tubing a	ınd Hallib Tbg Baler	ballot and tagged fill @
6/22/99 RIH with Mule Shoe Collar, SN, 2 3/8" tubing and Ha	allib PLS packer. Set Hallih PLS po	acker @ F0001 F-1-4-4
KB added in. TOTAL TUBING - 210 jts. NDBOP & NUWH. Rig blowing after each run.	up to swab. Initial FL @ 5500'. Ma	de 5 swab runs, recovered 15 bbls. Tubing
blowing after each run.	_	table, recovered to bots. Fabling
6/23/99 Check well pressures. CSG - 600 psi. Tbg - 400 ps down. Move off location. FINAL REPORT	i. Blow down tubing well started	flowing to nit let well t
down. Move off location. FINAL REPORT	wen started	nowing, to pit. Let well clean up to pit. Rig
I hereby certify that the information above is true and complete to the best of my kni		
	wiedge and belief.	
SIGNATURE: / LULY GWYTCH	TITLE: AGENT FOR CONOCC	DINC. DATE 6-29-99
TYPE OR PRINT NAME: VERUA JOHNSON	TELEPHONE NO. (070) 205 04	
(This space for State Use)	TELEPHONE NO. (970) 385-911	00 EX 1 20
(This space for State Lise) OFFICINAL SIGNED BY CHAPLIE T. PETRIN APPROVED BY	MINTY OH & CAS MAN	JUN 3 0 1999
CONDITIONS OF APPROVAL, IF ANY:	TITLE TITLE GAS INSPECTOR	JUN 3 0 1999
<u>. </u>		