

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

**Sundry Notices and Reports on Wells**

<p>1. <b>Type of Well</b> Gas</p> <hr/> <p>2. <b>Name of Operator</b> Manana Gas Inc</p> <hr/> <p>3. <b>Address &amp; Phone No. of Operator</b> 1002 Tramway Lane NE Albuquerque, NM 87122</p> <hr/> <p>4. <b>Location of Well, Footage, Sec., T, R, M</b> Sec. 24 T-29-N, R-11-W, NMPM, San Juan County Unit N, 790' FSL and 1510' FWL</p>	<p style="text-align: center;"><b>RECEIVED</b> AUG 20 1998 OIL CON. DIV. DIST. 3</p> <p>API # (assigned by OCD) <u>30-045-25241</u></p> <p>5. <b>Lease Number</b> Fee</p> <p>6. <b>State Oil &amp; Gas Lease #</b></p> <p>7. <b>Lease Name/Unit Name</b> Phyllis Hartman</p> <p>8. <b>Well No.</b> #1</p> <p>9. <b>Pool Name or Wildcat</b> <u>Otero</u> Bloomfield Chacra</p> <p>10. <b>Elevation:</b> 5442' GI</p>
---	--

**Type of Submission**

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

**Type of Action**

☐ Abandonment

☐ Recompletion

☒ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut off

☐ Conversion to Injection

**13. Describe Proposed or Completed Operations**

August 4 & 5, 1998:

RU rig and POH with 75 joints 1-1/4" tubing, no scale buildup. Run 5-1/2" wireline gauge ring to 2861'. Set 5-1/2" RBP at 2250' and load casing with water. Pressure test to 1000#, held 15 minutes OK. Recover RBP. Run Collar Locator from 2861' to 2200'; check depth of perforations. Set 5-1/2" wireline CIBP at 2720' to isolate lower Chacra perforations. Land 83 joints 1-1/4" tubing at 2670' with pin collar on bottom. RD and MO location.

SIGNATURE Ed Hartman President August 13, 1998  
Ed Hartman

(This space for State Use)

Approved by Chauhan

Title

DEPUTY OIL & GAS INSPECTOR, DIST. 3

Date

AUG 20 1998