

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)


1. oil ☐ well ☐ gas ☒ well ☐ other
2. NAME OF OPERATOR
Southland Royalty Company
3. ADDRESS OF OPERATOR
P.O. Drawer 570, Farmington, NM 87401
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1730' FSL & 1520' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Casing report

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐
☐
☐



5. LEASE
SF-080781
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Cain
9. WELL NO.
#15# m
10. FIELD OR WILDCAT NAME
Basin Dakota/Blanco Mesaverde
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 31, T29N, R09W
12. COUNTY OR PARISH
San Juan
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
5783' GL

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3-23-82 Drilled to TD 6725'. Ran 159 jts (6713') of 5-1/2", 15.5#, K-55 casing set at 6712'.

Cemented first stage with 345 sx Class "B" with 50/50 poz, 6% gel, 1/4# gel flake, tailed in with 50 sxs Class "B" with 2% CaCL2. Plug down at 12:01 am, 3-23-82.

Cemented second stage with 700 sxs Class "B", 50/50 poz, 6% gel, 1/4# gel flake, tailed in with 50 sxs Class "B" with 2% CaCL2. Plug down at 6:15 am, 3-23-82.

Cemented third stage with 500 sxs Class "B", 50/50 poz, 6% gel, 1/4# flocele/sx, tailed in with 50 sxs Class "B", with 2% CaCL2. Plug down at 10:30 am, 3-23-82. Good circulation. Top of cement at 300'.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Catherine Dwyer TITLE Secretary DATE March 24, 1982

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

MAR 30 1982

FARMINGTON DISTRICT
BY E. J. Beck