UNITED STATES DEPARTMENT OF THE INTERIOR

5. LEASE SF-080724-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME

GEOLOGICAL SURVEY	O. II MOIM, ALEOTTEE ON TRIBETORIE
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331+C for such proposals.)	8. FARM OR LEASE NAME
1. oil gu gas	Zachry
well AM well U other	9. WELL NO. 30
2. NAME OF OPERATOR	10. FIELD OR WILDCAT NAME
Union Texas Petroleum Corporation 3. ADDRESS OF OPERATOR	Armenta Gallup
P.O. Box 1290, Farmington, NM 87499	11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) AT SURFACE: 860' f/North; 570' f/East line	Sec. 33, T29N, R10W, NMPM 12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	San Juan New Mexico
AT TOTAL DEPTH: same as above	14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD) 5623 GR
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	
SHOOT OR ACIDIZE	(NOTE: Reparesults of multiple completion or zone
REPAIR WELL	change on Form 9-330.)
MULTIPLE COMPLETE	3 1983
CHANGE ZONES	ND MANAGEMENT
(other) reseeding and painting FARMINGTON F	RESOURCE AREA
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner. On 9/13/83, reseeding was completed using BLM Se was completed using Brown Federal Standard No.	eed Mix No. 2. The painting
was compressed as my	
Pipeline and well pad.	· ·
	IN EGET VED
	52120
	OIL CON. DIV.
Subsurface Safety Valve: Manu. and Type	Set @ Ft
18. I hereby certify that the laregoing is true and correct	•
Area Operation	ons Manager 9/16/83
R.D/Motto	
(This space for Federal or State of	rice use)
ADDDOVED BY	DATE

*See Instructions on Reverse Side

SEP 27 1983

ACCEPTED FOR RECORD