UNITED STATES DEPARTMENT OF THE INTERIOR • GFOLOGICAL SURVEY

· GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME SECTION
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir, Use Form 9–331–C for such proposals.)	8. FARM OR LEASE NAME
1. oil gas	Zachry 5 :
1. Oil gas other	9. WELL NO.
2. NAME OF OPERATOR	29
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Armenta Gallup : 11. SEC., T., R., M., OR BLK. AND SURVEY OR
P.O. Box 808, Farmington, New Mexico 87499	AREA SOOR BERNARD SOREL ON
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	Sec. 33, T29N R1OW NEW P.M.
AT SURFACE: 937 ft./N; 1785 ft./W line	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	San Juan 3 53 New Mexico
AT TOTAL DEPTH: Same as above	14. API NO. 25 25 25 25 25 25 25 25 25 25 25 25 25
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	<u> </u>
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5632 R.K.B.
<u> </u>	En :
FRACTURE TREAT	ED
PULL OR ALTER CASING DEC 10 19	NOTE: Report results of multiple completion or zone change on Form 9–330.)
MULTIPLE COMPLETE	·
CHANGE ZONES U. S. GEOLOGICAL U. S. GEOLOGICAL	survey : ខាន្ទម៉ូ តូ មូន ម៉ូ ម៉ូ
ABANDON* U. S. GEOLOGICAE (other)	SURVEY (California substitution of the california substitutio
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d	e all pertinent details, and give pertinent dates, irectionally drilled give subsurface locations and
measured and true vertical depths for all markers and zones pertinen	it to this work.)*
1. Spudded 14-3/4" surface hole at 7:30 P.M. 12/	/3/82.
2. Drilled 14-3/4" surface hole to 316 ft. R.K.I	3.
3. Ran 7 joints of 10-3/4", 40.50#, H-40 casing	and set at 346 It. R.K.B.
4. Cemented with 295 cu. ft. of class "B" with 2	2% CaCl ₂ . Plug down at 6:30 A.M.
12/4/82. Cement circulated to the surface.	무기되는 그 불림학생이다.
5. Waited on cement for 12 hours.	
	Å.
Subsurface Safety Valve: Manu. and Type	
18. I hereby certify that the foregoing is true and correct SIGNED SUPPLY E. WHAT TITLE Area Prod. Sup	pt. pare December 8, 1982
Kenneth E. Roddy (This space for Federal or State offi	
	•
APPROVED BYTITLETITLE	DATE

ACCEPTED FOR RECORD

Form Approved.

Budget Bureau No. 42-R1424

CRIOUS 7A BU

*See Instructions on Reverse Side

DEC 15 198?

FARMINGTON DISTRICT