UNITED STATES DEPARTMENT OF THE INTERIOR

DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	SF 047020-B
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME
1. oil gas cother	Congress 9. WELL NO.
2. NAME OF OPERATOR	11
Union Texas Petroleum Corporation	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Box 808, Farmington, New Mexico 87499	Wildcat Gallup 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	Sec. 35, T29N, R11W, N.M.P.M.
<pre>below.) AT SURFACE: 1905 ft./S; 830 ft./E line</pre>	12. COUNTY OR PARISH 13. STATE
AT TOP PROD. INTERVAL: Same as above	San Juan New Mexico
AT TOTAL DEPTH: Same as above 6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	5708 R.K.B.
ULL OR ALTER CASING	JRVEY
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is domeasured and true vertical depths for all markers and zones pertiner. 1. Spudded 14-3/4" surface hole at 12:30 P.M. 12 12. Drilled 14-3/4" surface hole to total depth of the surface hole at 12:30 P.M. 12 13. Ran 6 joints of 10-3/4", 40.50#, K-55 casing the surface with 326 cu. ft. of class "B" with 12.	irectionally drilled, give subsurface locations and to this work.)* 2/5/82. of 280 ft. R.K.B. and set at 274 ft. R.K.B.
	ulated to the surface.
5. Waited on Cement for 12 hours.	
ubsurface Safety Valve: Manu. and Type	Set :@ F

AGGEPTEN FOR RECORD

Form Approved.

Budget Bureau No. 42-R1424

*See Instructions on Reverse Side

DEC 15 1982

