

Caller Service 4104
Farmington, New Mexico 87499

CERTIFIED

13 MAR 1984

Union Texas Petroleum Corp.
P. O. Box 1290
Farmington, New Mexico 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) wells No. 43 and 44 Zachry, SW $\frac{1}{4}$ NW $\frac{1}{4}$ and SW $\frac{1}{4}$ NE $\frac{1}{4}$, sec. 33, T. 29 N., R. 10 W., San Juan County, New Mexico, lease Santa Fe 080724-A. As discussed with Bill Cooper of your company on March 5, 1984, the subject APD is rescinded and returned due to drilling not being commenced within one year of the approval date.

You are required to request surface rehabilitation instructions from this office because construction activities have occurred on the referenced drill sites.

Sincerely yours,

R. B. [Signature]
Area Manager

Enclosure

cc: NMOCC

RECEIVED
MAR 14 1984
OIL CON. DIV.
DIST. 3

ABANDONED LOCATION

3/18/83

30-045-25627

F

F. Loc. 1980/N;660/W Elev. 5700 GL Spd. _____ Comp. _____ TD _____ PB _____

Casing S. _____ @ _____ W _____ Sx. Int. _____ @ _____ W _____ Sx. Pr. _____ @ _____ W _____ Sx. T. _____ @ _____ T Gas

Csg. Perf. _____ Prod. Stim. _____

Grav. _____ 1st Del. Gas _____

I.P. _____ BO/D _____ MCF/D After _____ Hrs. SICIP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS		NI/D <input checked="" type="checkbox"/>	Well Log	TEST DATA							Ref.No.
Ojo Alamo		C-103	Plat X	Schd.	PC	Q	PW	PD	D		
Kirtland		C-104	Electric Log								
Fruitland			C-122								
Pictured Cliffs		Ditr	Dfa								
Chacra		Datr	Dac								
Cliff House											
Menefee											
Point Lookout											
Mancos											
Gallup											
Greenhorn											
Dakota											
Entrada											
		Acres 40									

P
o
o
Armenta Gal. Co. SJ S 33 T 29N R 10W U E Oper. Union TX Petroleum Lse. Zachry

No. 43

Zachry #43

E-33-29N-10W

UNION TEXAS PETROLEUM CORPORATION