

STATE OF NEW MEXICO

ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE

TONEY ANAYA

1000 RIO BRAZOS ROAD AZTEC, NEW MEXICO 87413 (505) 334-6178

April 4, 1986

Slayton Oil Corp. P.O. Box 150 Farmington, NM 87499

Re: Northwest Cha Cha Unit #41-28, A-28-29N-14W

Northwest Cha Cha Unit #32-20, G-20-29N-14W

Gentlemen:

Recent NMOCD bradenhead testing on the referenced wells revealed incorrect information on the well signs. The sign at the Northwest Cha Cha Unit #41-28 showed the range to be 17W. The correct location is 14W. The footages on the sign at the Northwest Cha Cha Unit #32-20 should read 2290 feet from the north line and 1825 feet from the east line.

You are hereby directed to make the necessary corrections or repairs within 30 days. Copies of the 1986 bradenhead tests on all wells in the Northwest Cha Cha Unit are enclosed for your reference.

Yours truly,

Carolyn J. Taplin

Field Representative

Jakon Care Care

CJT/dj Enclosure

xc: Prentiss Childs

VIC File
Well Files
Operator File