

Elm Ridge Resources Inc.  
Callow #7  
Sec.33-T29N-R13W  
San Juan County, New Mexico

SLOPE TESTS

DEPTH

296'  
831'  
1315'  
1740'

HOLE DEVIATION

3/4  
1/2  
1  
1 1/4

I, Doug Endsley, being first duly sworn, depose and state that the above and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

Doug Endsley

Subscribed and sworn before me this 18th day of May, 1999

Alfred P. M. [Signature]

Notary Public

My Commision Expires

March 18, 2002

RECEIVED  
MAY 19 1999

OIL CON. DIV.  
DEPT. 8