Form 3160-5 (November 1983) (Formerly 9-331) <b>DEPA</b>	UNITED STATES ARTMENT OF THE INTERIO	SUBMIT IN TRIPLICATE*  (Other instructions on reverse side)	Porm approved. Budget Bureau No. 1004-0135 Expires August 31, 1985 5. LEASE DESIGNATION AND SERIAL NO.
BUREAU OF LAND MANAGEMENT_			SF-077865
	NOTICES AND REPORTS C		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDKY I	proposals to drill or to deepen or plug be PPLICATION FOR PERMIT—" for such pr	ack to a different reservoir.	
Use "AI	PLICATION FOR PERMIT—" for such pr	oposals.)	N/A 7. UNIT AGREEMENT NAME
1. OIL GAS NZ			
WELL WELL OT	HER		N/A 8. FARM OR LEASE NAME
2. NAME OF OPERATOR Union Texas Petroleum			ALBRIGHT
3. ADDRESS OF OPERATOR			9. WELL NO.
<del>-</del> -	64. Farmington, New Mexi	co 87 <b>4</b> 01	18A
4. LOCATION OF WELL (Report location)	ation clearly and in accordance with any	State requirements.	10. FIELD AND POOL, OR WILDCAT
375 U.S. Highway 64, Farmington, New Mexico 87401  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  At surface			Blanco Mesaverde
1190' FNL & 1015' FWL OCT 08 1986			11. SEC., T., B., M., OR RLE. AND SURVEY OR AREA
			Section 22-T29N-R10W
14. PERMIT NO.	15. ELEVATIONS (Show whether DF,	BUREAU OF LAND MANAGEME	12. COUNTY OR PARISH 13. STATE
	5618' GL, 5630' KB	FARMINGTON RESOURCE ARE	San Juan NM
16. Char	L. A Bou To Indicate N		· ·
Clieba / Appropriate Box 10 meteors of the control			UBNT REPORT OF:
NOTICE OF	INTENTION TO:	208880	D CONTRACTOR:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
SHOUL OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABANDONMENT* Droduction CSQ X
REPAIR WELL	CHANGE PLANS	(Other) Inter. &	a of multiple completion on Well
(Other)			s of multiple completion on Well pletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLET proposed work. If well is nent to this work.) •	ED OPERATIONS (Clearly state all pertinent directionally drilled, give subsurface locat	t details, and give pertinent dates ions and measured and true verti	s, including estimated date of starting any cal depths for all markers and sones perti-
into surface pip gilsonite/sk, ta bbls preflush to Dril 6-1/4" hole liner from 2218'	pe with 210 sxs (603 cu.failed by 100 sxs (118 cu.o surface. W.O.C. Presse out of casing with gas to 4710' KB. Cement in DZ containing 4% gel, 6-1	t.) 65/35 POZ contai ft.) Cl "B" w/2% CaC ure test casing and to 4710' KB. Run 4-side intermediate ca/4# gilsonite/sk and	12. Circulate 16 of 20 BOP to 2000 psi. Held OK. 1/2", 10.50#, K-55, ST&C sing with 275 sxs (432 10# salt/sk. Circulate
			09 1986 N. DIV.
		<u> </u>	U9 1986 W
		OIL CO	)A.
		Nic	IV. DIV
		5/3	7. 3 · · · ·
15. I hereby certify they the fore	going is true and correct/		
SIGNED Adat		ermit Coordinator	ACOEPTED FOR RECORD
			VOOEL JED TOURISHOOM
(This space for Federal or St			DCT 0 9 1986
CONDITIONS OF APPROVAL	L, IF ANY:		FARMINGTON RESOURCE AREA
			1 1 10 1 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1

\*See Instructions on Reverse Side NMOCC