

| <u>DEPTH</u> | <u>DEVIATION</u> |
|--------------|------------------|
| 459' | 1/4° |
| 998' | 1/2° |

RECEIVED
JUL 11 1968
OIL CON. DIV.
DIST. 3

THIS IS TO CERTIFY that to the best of my knowledge the above tabulation details the deviation test taken in BHP Petroleum (Americas) Inc. Gallegos
Canyon Unit No. 363 Located 1265' FNL and 180' FEL Section 26, T29N, R13W in
San Juan County, New Mexico

Handwritten Signature
PETROLEUM ENGINEER

Geraldine B. B. B.
Notary Public