

Hare #296

G-23-29N-10W

SOUTHLAND ROYALTY CO.

F

30-045-27272

4-6-89

F. Loc. 1450/N; 1565/E Elev. 5740 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx. Int. @ W Sx. Pr. @ W Sx. T. @ _____
 Csg. Perf. Prod. Stim.

BO/D Grav. _____ 1st Del. Gas _____
 I.P. MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil _____

TOPS	NITD X	Well Log	TEST DATA							
Ojo Alamo	C-103	Plat X	Schd.	PC	Q	PW	PD	D	Ref.No.	
Kirtland	C-104	Electric Log								
Fruitland		C-122								
Pictured Cliffs	Ditr	Dfa								
Chacra	Datr	Dac								
Cliff House	N/320.00 Acres									
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

T Gas
R
A
N
SP
o
o

BasinFr.CoalCo. SJ s 23 T 29N R 10W UG Oper. Southland Royalty Co.Lse. Hare

No. 296

NM-03179 (WC) et al.
3162.3-1(F) (019)

JAN. 04 1990

Meridian Oil Incorporated
P. O. Box 4289
Farmington, NM 87499

Gentlemen:

Enclosed are your Applications for Permit to Drill (APDs) for the following wells.

- ✓ 1. No. 700 Aztec, 810' FSL & 790' FWL, sec. 14, T. 28 N., R. 1² W., San Juan County, New Mexico, lease NM-03179.
- ✓ 2. No. 103 Hubbard Com, 1930' FNL & 1490' FEL, sec. 22, T. 32 N., R. 11 W., San Juan County, New Mexico, lease SF-078312. *2k pool.*
- ✓ 3. No. 101 Hubbard Com, 790' FSL & 2115' FWL, sec. 15, T. 32 N., R. 12 W., San Juan County, New Mexico, lease SF-078312.
- ✓ 4. No. 100 Hubbard, 1000' FSL & 790' FWL, sec. 11, T. 32 N., R. 12 W., San Juan County, New Mexico, lease SF-078312.
- ✓ 5. No. 707 Hancock, 1705' FSL & 1550' FWL, sec. 23, T. 28 N., R. 9 W., San Juan County, New Mexico, lease NM-04209.
- ✓ 6. No. 296 Hare, 1450' FNL & 1565' FEL, sec. 23, T. 29 N., R. 10 W., San Juan County, New Mexico, lease SF-076958.

The subject APDs are rescinded and returned pursuant to your written instructions dated November 29, 1989.

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill site. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in an assessment of liquidated damages.

Sincerely,

ABANDONED LOCATION

for John L. Keller
Chief, Branch of Minerals

6 Enclosures

cc:
NMOCD, Aztec

RECEIVED
JAN 08 1990
OIL CON. DIV.
DIST. 3