

FC Fed Com #19

B-06-29N-11W

1 Conoco, Inc.

F


30-045-28044

07-25-90

F. Loc. 794/N; 1535/E Elev. 5808 GL Spd. _____ Comp. _____ TD _____ PB _____
 Cu. ft. Cu. ft. Cu. ft.
 Casing S. @ W Sx Int. @ W Sx Pr. @ W Sx T. @
 Csg. Perf. Prod. Stim.

T
R
A
N
S

BO/D Grav. _____ 1st Del. Gas
 I.P. MCF/D After _____ Hrs. SICP _____ PSI After _____ Days GOR _____ 1st Del. Oil

TOPS	NITD	X	Well Log	TEST DATA						
				Schd.	PC	Q	PW	PD	D	Ref.No.
Ojo Alamo	C-103		Plot	X						
Kirtland	C-104		Electric Log							
Fruitland			C-122							
Pictured Cliffs	Ditr		Dfa							
Chacara	Datr		Dac							
Cliff House										
Menefee										
Point Lookout										
Mancos										
Gallup										
Greenhorn										
Dakota										
Entrada										

P
o
o

BasinFrCoal Co. SJ S 06

T 29N R 11W UB Oper.

Conoco, Inc.

Lse. FC Fed Com

No. 19



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Farmington Resource Area
1235 Laplata Highway
Farmington, New Mexico 87401



SF-046563 et al IN RE (W.C.) REFER TO:
3162.3-1.0 (019)

OCT. 07 1991

RECEIVED
OCT 8 1991
OIL CON. DIV.
DIST. 3

Conoco, Inc

~~Mesa Operating Limited Partnership~~
P.O. Box 2009
Amarillo, TX 79189

Gentlemen:

Enclosed are your Applications for Permit to Drill well Nos:

1. 17 FC Federal, sec. 34, T. 28 N., R. 10 W., San Juan Co., NM lease
SF-046563.
2. 18 FC Federal, sec. 9, T. 29 N., R. 12 W., San Juan Co., NM lease
NM-021119.
3. 19 FC Federal Com, sec. 6, T. 29 N., R. 11 W., San Juan Co., NM lease
NM-020504.
4. 30 FC Federal Com, sec. 3, T. 29 N., R. 14 W., San Juan Co., NM lease
SF-079968.
5. 31 FC Federal Com, sec. 33, T. 30 N., R. 14 W., San Juan Co., NM lease
SF-079968.
6. 36 FC Federal, sec. 33, T. 30 N., R. 14 W., San Juan Co., NM lease
SF-079968.
7. 38 FC Federal Com, sec. 33, T. 31 N., R. 11 W., San Juan Co., NM lease
SF-078097.
8. 39 FC Federal Com, sec. 14, T. 30 N., R. 11 W., San Juan Co., NM lease
SF-078138.

The subject APDs are rescinded and returned due to drilling not being commenced within one year of the approval date.

ABANDONED LOCATION

You are required to request surface rehabilitation instructions from this office if construction activities occurred on the referenced drill sites. If this office does not receive comment within 30 days, we will presume that no construction occurred and proceed accordingly. Later discovery that construction activities have in fact occurred, may result in assessment of liquidated damages.

Sincerely,



for John L. Keller
Chief, Branch of Mineral Resources

Enclosures

cc:

New Mexico Oil Conservation Division, 1000 Rio Brazos Rd., Aztec, NM 87410