## TABULATION OF DEVIATION SURVEYS

## BHP PETROLEUM (AMERICAS) INC. GALLEGOS CANYON UNIT NO. 501 API NO. 30-045-28052

<u>DEPTH</u>	<b>DEVIATION</b>
1077'	3/4°
1447'	3/4°

**AFFIDAVIT** 

This is to certify that to the best of my knowledge the above tabulation details the deviation tests taken in the BHP PETROLEUM (AMERICAS) INC.'S Gallegos Canyon Unit No. 501 located 1655' FSL & 2315' FEL of Section 13, T29N-R13W in San Juan County, New Mexico.

Signed Reverly Comer

THE STATE OF TEXAS)

SS.

COUNTY OF HARRIS )

BEFORE ME, the undersigned authority, on this day personally appeared <u>Beverly Comer</u> known to me to be <u>Production Technician</u> for <u>BHP Petroleum (Americas) Inc.</u> and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Notary Public in and for said County and State this 11th day of 1991.

My Commission Expires

Notary Publi

FIOSEWARIE MUPPHY
NOTARY PUBLIC, STATE OF TEXAS
MY COMMISSION EXPRES
APR. 20, 1993