UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

·			
	Sundry Not	tices and Reports on	Wel/s
1. Type of W	rell Single	RECEIVED	5. Lease Number SF-068990 6. If Indian, All. or Tribe Name
2. Name of C		OIL CON. DIV.	7. Unit Agreement Name
PO Box 4 4. Location	Phone No. of Opera	tor 87499 (505) 326-970 ec., T, R, M	30-045-28895 10. Field and Pool Basin Ft Coal 11. County and State
12. CHECK A	PPROPRIATE BOX TO IN		San Juan Co, NM ICE, REPORT, OTHER DATA
No	otice of Intent absequent Report inal Abandonment	Type of Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other -	Change of Plans New Construction Non-Rautime Fracturing
04-01-9 04-02-9 04-03-9 04-04-9 04-05-9 05-05-9 07-01-9 07-02-9	1905'. RIH w/scra 33 Ran CBL-CCL-GR. F w/sand & foam. Fl 33 TIH w/coil tbg un 33 Flow to clean up. 33 Flow well. TIH w/ hole pressure bui 33 MOL. Frac Fruitla 33 MOL&RU. TIH, tag Blow w/air & wtr. 33 Blow w/air. Drl C 1785'. Drill & ci 33 Blow to pit. Ran 1750'. F nipple 6	er to 1390'. Drl out in aper to 1850'. Circ was 27 csg 3000#. Perf 166 low well. The state of th	bom. SI for 7 day bottom to bom. Moved off. air. Pull up to 1670'. the to btm, tag fill @ oit. J-55 EUE 10rd tbg landed @ H. Released rig.
Signed lass		foregoing is true and Title Regulatory	Affairs Date 7/6/93
APPROVED BY	for Federal or Stat	ce Office use)Title	HUL 1PA 1993
COUNTITOR OF	AFFROVAL, II dny:	PANCOCO	FARMINGTON DISTRICT OFFICE

BY 205