## TABULATION OF DEVIATION SURVEYS

BHP PETROLEUM (AMERICAS) INC. GALLEGOS CANYON UNIT NO. 519 API NO. 30-045-29057

PECETVED

MAY 1 7 1994

OIL COXL DIVA

DEPTH	<b>DEVIATION</b>
162'	1°
645 <i>'</i>	3/4°
1140'	1°
1545′	1°

**AFFIDAVIT** 

This is to certify that to the best of my knowledge the above tabulation details the deviation tests taken in the BHP PETROLEUM (AMERICAS) INC.'S Gallegos Canyon Unit No. 519 located 885' FSL & 1450' FWL of Section 21,T-29-N,R-12-W in San Juan County, New Mexico

Signed Cal Kalbe

THE STATE OF TEXAS)

SS.

)

COUNTY OF HARRIS

BEFORE ME, the undersigned authority, on this day personally appeared <u>Carl Kolbe</u> known to me to be <u>Regulatory Affairs</u> <u>Representative</u> for <u>BHP Petroleum (Americas) Inc.</u> and to be the person whose name is subscribed to the above statement, who, being by me duly sworn on oath, states that he has knowledge of the facts stated herein and that said statement is true and correct.

SUBSCRIBED AND SWORN TO before me, a Natary Public in and for said County and State this 4th day of 1993.

MICHELLE WISE MY COMMISSION EXPIRES April 4, 1998

Notary Public

My Commission Expires