



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemnr.state.nm.us/ocd/District III/3distr.htm](http://nemnr.state.nm.us/ocd/District%20III/3distr.htm)

MECHANICAL INTEGRITY TEST REPORT
(~~FEA~~ or UIC)

Date of Test 9-25-02 Operator Kenson Oper Co. API # 30-045-29187

Property Name NW Cha Cha Well # 26 Location: Unit I Sec 22 Twn 29 Rge 14

Land Type:

State _____
Federal _____
Private _____
Indian X

Well Type:

Water Injection X
Salt Water Disposal _____
Gas Injection _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): N

TA Expires: _____

Casing Pres. _____
Bradenhead Pres. 6
Tubing Pres. _____
Int. Casing Pres. _____


Tbg. SI Pres. _____
Tbg. Inj. Pres. ~~1000~~ 1000

Max. Inj. Pres. _____

Pressured annulus up to 535 psi. for 30 mins. Test passed failed

REMARKS:

Pressure went to 585 psi - thermal expansion. Annulus took
18 bbls of water to fill - there was a lot of air in annulus.




By Jeff Hunter
(Operator Representative)

Witness Bruce Marti
(NMOCD)

(Position)

REVISED 11-17-98



92502
Phoenix Hydroco
Operating #26
NW Chainiform
END Chainiform
Lead #14-20-6037199M/T
NEWSEY
SEC 12, 129N, 64W
2:07pm to 2:37pm
MC
SAN JUAN COUNTY
NM
J.S.
1-0000-T

PRINTED BY THE FOXBORO COMPANY, FOXBORO, MASS. U.S.A. HWS0000
8 P.M. 7 P.M. 6 P.M.