

MERRION


OIL & GAS

Field Com No. 1E
API #30-045-29517
Section 5, T29N, R11W
San Juan County, New Mexico

SLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>		<u>Depth</u>	<u>Hole Deviation</u>
#1	90'	1/4°	#9	3256'	1/2°
#2	179'	1/2°	#10	3790'	3/4°
#3	240'	1/2°	#11	4285'	1°
#4	825'	1°	#12	4756'	3/4°
#5	1231'	1°	#13	5257'	3/4°
#6	1730'	1/2°	#14	5569'	1/4°
#7	2226'	3/4°	#15	6067'	1/2°
#8	2726'	1°	#16	6536'	1/2°
			#17	6787'	3/4°

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.


Steven S. Dunn

Subscribed and sworn before me this 27th of October, 1998

State of New Mexico }
 } ss
County of San Juan }


Esther J. Greeyes
Notary Public

My Commission Expires: August 7, 2002

