

# MERRION

OIL & GAS

HUT No. 1  
API #30-045-29518  
E Section 8, T29N, R11W  
San Juan County, New Mexico

## SLOPE TESTS

	<u>Depth</u>	<u>Hole Deviation</u>
#1	281'	0.75°
#2	801'	1.00°
#3	1300'	0.75°
#4	1800'	0.50°
#5	2298'	0.75°
#6	2799'	1.00°
#7	3328'	1.50°
#8	3800'	2.0°


RECEIVED  
MAR - 3 1998  
OIL CON. DIV.  
DIST. 3

I, Steven S. Dunn, being first duly sworn, depose and state that the attached and foregoing depth and hole deviation figures are true and correct to the best of my information and belief.

  
Steven S. Dunn

Subscribed and sworn before me this 2nd day of March, 1998

State of New Mexico    }  
                                      } ss  
County of San Juan     }

  
Esther J. Greyeyes  
Notary Public

My Commission Expires: August 7, 1998