



P O. Box 900, 5651 US Hwy. 64 ▪ Farmington, New Mexico 87499
(505) 327-4935 ▪ **24 Hour Dispatch (505) 325-6892** ▪ (505) 327-0416

DATE: 6-25-98

RIG # 42

CONOCO INC.
10 DESTA DRIVE, SUITE 100W
MIDLAND, TX. 79705

THIS LETTER IS TO CERTIFY THAT BIG A WELL SERVICE DID RUN DEVIATION SURVEYS
AT THE LISTED DEPTH ON YOUR HOUCK # 2M WELL, IN SECTION 11, T-29-N, R-10-W
IN SAN JUAN COUNTY, NEW MEXICO.

DEPTH	DEGREE DEVIATION	DEPTH	DEGREE DEVIATION
271	1/2	2980	3/4
801	3/4	3480	3/4
1200	1-1/2	4294	1/4
1697	1-3/4	5078	1/4
2193	1-1/4	5984	1
2504	3/4	6514	1-3/4

TO THE BEST OF MY KNOWLEDGE, I SWEAR THIS INFORMATION TO BE TRUE.

SINCERELY,

JOHN K. RICHARDSON
DRILLING MANAGER

Notary Public

My commission expires: 6/9/00