Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135

Expires: March 31,/1993

5. Lease Designation and Serial No.

Completion or Recompletion Report and Log form).

SUNDRY NOTICES AND REPORTS ON WELLS SF-079968 Do not use this form for proposals to drill, or to deepen or reentry to a different reservoir. 65 If Indian, Allotte or Tribe Name Use "APPLICATION FOR PERMIT--" for such proposals SUBMIT IN TRIPLICATE 7. If Unit or CA, Agreement Designation 1. Type of Well Oil Well Gas Well Other 8. Well Name and No. WF Federal 3-1 2. Name of Operator Richardson Operating Company 9. API Well No. 30-045-30202 3. Address and Telephone No. 1700 Lincoln, Suite 1700, Denver, Colorado 80203 (303) 830-8000 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, T, R, M, or Survey Description) Twin Mounds Fruitland Sand PC Ext. 1265' FNL, 1095' FWL 11. County or Parish, State Sec. 3-T29N-R14W San Juan County, NM CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12. TYPE OF SUBMISSION TYPE OF ACTION Abandonment Change of Plans Notice of Intent Recompletion New Construction Plugging Back Non-Routine Fracturing Subsequent Report Casing Repair Water Shut-Off Altering Casing Conversion to Injection Final Abandonment Notice Surface Casing/Cementing Dispose Water Other: see below (Note: Report results of multiple completion on Well

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.

If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markets and zones pertinent to this work.)*

Well completed as per attached treatment report



hereby certify that the foregoing is true and correct great: Cally	Title: Land Manager	ACGEPTED FOR RECORD
	Title:	Date: NOV 0 1 2000
Approved by: Conditions of approval, if any: itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly attements or representations as to any matter within its jurisdiction.		4

RICHARDSON OPERATING COMPANY

FRACTURE TREATMENT REPORT

Operator:	or: Richardson Operating Company August 17, 2000			Well Name:	WF Federal 3-1						
Date:				<u>-</u> _							
Field:	Pictured Cliffs			Location:	3-29N-14W		County:	San Juan	State:	NM	
Stimulatio	n Company:	Schlumberger		Supervisor:	-						
Stage #:	1/1										
Sand on location (design): 56,804		_Weight ticket:	56,804		_Size/type:	20/40 A	rizona Sand				
Fluid on lo	ocation:	No. of Tanks:	2	Strap:	40	Amount:	800	_ Usable:		760	
Perforati	ons						·				
		Depth:	985'-995'		-	Total Holes:	40	_	PBTD:	1147.35	
		Shots per foot:	4		-	EHD:	0.41	_			
Breakdo	wn										
		Acid:	500		-						
		Balls:	N/A		_						
		Pressure:	625		-	Rate:	3		-		
Stimulat	ion						 				
		ATP:	599	<u> </u>	-	AIR:	24	-	-		
		MTP:	1877	,	-	MIR:	31.3	3			
				Sand Stage	Pressure			Breaker test	-		
	1015	500		pad	595						
	ISIP			1 ppg	595 586			break in 53 m	ine		
	5 min 10 min			2 ppg 3 ppg	577			Dieak III 55 II	11113.		
	15 min			4 ppg	558						
	Job Complet		26 hrs.	,,,,	Date:	8/17/00	_	Start flow back	·	N/A	
	Total Fluid F	Pumped:	683 <u>I</u>	obls	_						
	Total Sand Pumped:56,8		304	Total Sand or		Formation: 57		7,431			
	Total Nitroge	en Pumped:	N/A				_				
Notes:			· · · · · · · · · · · · · · · · · · ·								
1.10103.											
I											