

(SUBMIT IN TRIPPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Navajo

Window Rock, Arizona

Allotted Shell Oil

Lease No. 14-20-602-5076

SUNDRY NOTICES AND REPORTS ON WELLS

INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

May 8, 1961

Window Rock 16

Sec. 16 is located 2310 ft. from 1/4 line and 1650 ft. from 1/2 line of sec. 16

Window Rock 16

(Sec. and Sub. No.)

29N

(Twp.)

10W

(Range)

10N

(Meridian)

Window Rock Gallup Extension

(Field)

San Juan

(County or Subdivision)

New Mexico

(State or Territory)

OL

Elevation of the drill hole above sea level is 5174 ft.

DETAILS OF WORK

(Give names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate reworking jobs, cementing points, and all other important proposed work)

Plugged from 167' TD to surface with 9 sack cement. Placed marker.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

By Royal Development Company

P.O. Box 1299

Albuquerque, New Mexico

By Thos. F. Stringer

Thos. F. Stringer, Production Eng.