Form 3160-5 (June 1990)

@ 1730 on 9-19-91.

or representations as to any matter within its jurisdiction

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM	LAPPRO	OVED	
Budget Burn	eau No.	1004-013	35
Expires	March	31, 1993	

5. Lease Designation and Serial No.

6. If Indian, Allottee or Tribe Name

SF-078999

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

7. If Unit or CA, Agreement Designation

1 Type of Well		San Juan 31-6 Unit
Oil Gas Other		8. Well Name and No.
2. Name of Operator		24
Phillips Petroleum Company		9. API Well No.
3 Address and Telephone No.		
	ngton, NM 87401 (505) 599-3412	10. Field and Pool, or Exploratory Area
4 Location of Well (Footage, Sec., T., R., M., or Survey D	escription)	Basin Dakota
Unit K, 1470' FSL & 1490' F		11. County or Parish, State
Sec. 27, T31N, R6W		Rio Arriba, NM
12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REF	PORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTIO	ON
Notice of Integr	Abandonment Recompletion	Change of Plans New Construction
XX Subsequent Report	Plugging Back	Non-Routine Fracturing
TET 1 (19)	Casing Repair	Water Shut-Off
Final Ahandonment Notice	Altering Casing	Conversion to Injection
CALCON		Dispose Water
D.5T. IS		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed of Completed Operations (Clearly state at	I pertinent details, and give pertinent dates, including estimated date of state all depths for all markers and zones pertinent to this work.)*	

MI & RU Drake #26 to repair casing leaks and re-stimulate well. Isolate & repaired 4-1/2" casing leaks from 1402' to 3184'. All leaks test @ 500 psi and held 30 minutes w/35 psi maximum pressure loss. RU HLS and perf'd Dakota from 7940'-8034' KB. RD perforators. RU to frac well. Frac well @ 26 BPM @ 6400 psi treating pressure. Pmpd 60,000# 20/40 sand @ 3.75 ppg sand concentration. Flow back. Rec. 240 bbls. frac fluid. Clean out well to 7400'. Total frac water recovered 745 bbls. SI csg pressure 720 psi, bled to pit. RIH w/2-3/8" tbg to 7830'. Filled csg w/68 bbl pkr fluid. Pressure test pkr to 500 psi, held okay. NU and pressure test master valve assembly, test okay, opened well to atmosphere, no flow. RD & released rig

NOTE: PPCo inadvertently failed to obtain prior approval. Ed Hasely w/PPCo spoke w/Steve Mason on 9/6/91 and was told to submit the subsequent report detailing the work.

(This space for Federal or State office use)	T-1	
approved by	Title	Dete

*See instruction on Reverse Side