

**Key Energy Services, Inc.**

Four Corners Division
P.O. Box 900
5651 US Highway 64
Farmington, NM 87499

Phone: 505-327-4935
Fax: 505-327-4962

October 16, 2000

Rig No. 47

Phillips Petroleum Company
5525 Hwy 64 NBU 3004
Farmington, NM 87401

Attn: Patsy Clugston

C-26-31N-6W

30-039-26433

This letter is to certify that Key Energy Services, Inc., did run deviation surveys at the listed depths on the San Juan 31-6 #42M well in ~~S31-T36N-R66W~~, in Rio Arriba county, New Mexico.

Depth	Deviation	Depth	Deviation
153'	1/2°	4342'	1°
308'	1/4°	4867'	1 3/4°
559'	1/4°	5363'	1 1/4°
1080'	1°	5893'	1 3/4°
1580'	1°	6388'	2°
2077'	3/4°	6634'	1 3/4°
2575'	1°	7160'	1 1/2°
3072'	1/2°	7667'	1 1/2°
3570'	3/4°	8010'	1 1/4°
3820'	1°		

To the best of my knowledge, I swear this information to be true.

Sincerely,

J.D. Griffith
Drilling contract manager

Notary Public
My commission expires: 6/26/05