

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Pe
Lease No.	01.3860-B
Unit	Aurphy

SUNDRY NOTICES A	ND REPORTS ON WELLS
WALLES OF WALLESON TO DOUG	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.
NOTICE OF INTENTION TO CHANGE PLANS	1
NOTICE OF INTENTION TO TEST WATER SHOT-OF	1 1
NOTICE OF INTENTION TO RESORTE OR RELATIVE WELL-	, II
1	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	
(INDICATE ABOVE BY CHECK MARK	NATURE OF REPORT, NOTICE, OR OTHER DATA)
Well No is located \$50ft. from	N line and 1550 ft. from W line of sec.34
(½ Sec. and Sec. No.) (Twp.)	(Range) (Meridian)
Astoc Fictured Cliffs (County o	r Subdivision) (State or Territory)
The elevation of the derrick floor above sea lev	
The elevation of the derrick noor above sea lev	/CI 15 #
DETAI	LS OF WORK
(State names of and expected depths to objective sands; show size ing points, and all o	es, weights,'and lengths of proposed casings; indicate mudding jobs, cement ther important proposed work)
To the intended to drill a wall thru	the Pictured Cliff formation using rotary
C-sing Program: 9 5/8" at 120' with 125 mack 5 1/2" at 2205' with 75 mack	is regular count circulated to surface. Is regular communt, 75 sacks Posmix.
The Bi 1/4 of Section 34 is delicate	d to this well.
R/2 HH/4 SF 043260-B, W/2 HH/4 SF 04	3260-A.
I understand that this plan of work must receive approval in	writing by the Geological Survey before operations may be commenced.
Company Il Paso Intural Cas Campany	
Address 997	
Permington New Mexico	By C. Check
	Title Petrolem Regineer