



30 N

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Santa FeLease No. 078213

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

November 25, 1960

Well No. 2-26 is located 1140 ft. from N line and 990 ft. from E line of sec. 26

<u>NE NE Section 26</u> (1/4 Sec. and Sec. No.)	<u>30 North 13 east</u> (Twp.) (Range)	<u>NMPM</u> (Meridian)
<u>Wildcat</u> (Field)	<u>San Juan County</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)

The elevation of the derrick floor above sea level is _____ ft. 5792 G. L.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Operator ran 6583' of 4-1/2", 9.5% & 11.6%, ran centralizers and scratchers through interval 6350-6500'. Circulated and reciprocated for one hour prior to cementing.

Cemented w/280 ex 1:1 Diamix w/2% gel. Used top and bottom rubber plugs. Displaced top plug with 106 BW and bumped same with 2000 psi pressure.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company COMPASS EXPLORATION, INC.Address 1645 Court Place
Denver, ColoradoBy P. J. Farrelly
P. J. FARRELLYTitle Geologist