

STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

New Mexico
Land Office 3744
Lesse No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF REDRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 13, 1951
Stewart 2 990 1065 20
Well No. _____ is located _____ ft. from [N] line and _____ ft. from [E] line of sec. _____
S. 7. Sec. 20 T-30N R-10W NE1/4
W 1244 (1/4 Sec. and Sec. No.) T-30N (Range) Meridian New Mexico
(Field) (County or Subdivision) (State or Territory)


The elevation of the derrick floor above sea level is 6153 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cement-
ing joints, and all other important proposed work)
Hole was bailed dry after drilling plug with cable tools and tested for water
shut-off; no water. Well was shot. 9/9/51 with 200 Qts OMC. 2741' to 2653'
well was cleaned out to T.S. of 2741'; ran 129 joints of 1" std. line pipe for
siphon landed at 2727'. Tree is set and well shut in for test.


I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Behm Oil Corporation
Address Box 1175
Marathon, New Mexico
By J. B. Howell
Geological Survey
Title _____



DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
UNITED STATES
(SUBMIT IN TRIPLICATE)

Land Office
Lease No.
Unit



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANT	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PUMP OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(PRINT ABOVE BY CHECK MARK NATURE OF REPORT, NOTED OR OTHER DATA)

Well No. _____ is located _____ from _____ line and _____ from _____ line of sec. _____

County _____ (County or Territory)
State _____ (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show areas, weights, and lengths of proposed casing; indicate mudding jobs, cementing points, and all other important proposed work)

I am interested that this plan of work be received and that the work be carried out in accordance with the plan of work submitted.

Company _____

Address _____

[Handwritten signature]

THE