

(SUBMIT IN TRIPLICATE)

Indian Agency Navajo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee _____

Lease No. 25-22-42-2731

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 2, 1958

Well No. 1 is located 660 ft. from N line and 660 ft. from E line of sec. 19
19 (1/4 Sec. and Sec. No.) 30E 34W (Range) NEW MEXICO (Meridian)
Wilcox (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 5127 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

90° 35/8 Surface Drill Test from 673 to 718. Sulphur water
 Run Electric Log from 1467 to top of hole. Sulphur water
 in Dakota. Plug to abandon.

Plug to abandon - Cement from 1490 to 1100 - 750 to 900 ft.
 10 ft. in bottom surface. 5 sacks in top of surface.



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company D. F. Sudduth
 Address 1313 Eleonfield Rd.
Farmington, New Mexico
 By _____
 Title Agent