


STATE OF NEW MEXICO
OIL CONSERVATION
COMMISSION
DISTRICT NO. 3
Phone 99 P. O. Box 697
AZTEC, NEW MEXICO

(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

State Fe
Land Office 002008
Lease No. _____
Unit _____



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

September 20, 1951

Well No. 2-7 is located 990 ft. from N line and 1450 ft. from E line of sec. 23

N. 1/4 Sec. 23 (1/4 Sec. and Sec. No.) T-10-N R-9-E (Twp.) 100W (Range) 100W (Meridian)
Blanco (Field) San Juan (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 6001 ft. N. 1.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well was deepened for original T. D. of 4531' to 5095' with rotary tools; then cable rig was moved in and well cleaned out to 50 30. Well was shot with 930 lbs. of dynamite. 4500' to 50 95' has 2" 4.75 lb. tubing landed at 4544'. True is set and well shut in for test.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Elkhart Corporation

Address Box 1175


Farmington, New Mexico

By J. H. Howell
J. H. Howell
Title Superintendent

Land Office _____
 Lease No. _____
 Unit _____

**UNITED STATES
 DEPARTMENT OF THE INTERIOR
 GEOLOGICAL SURVEY**

(SUBMIT IN THIS CASE)



SUMMARY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLUGS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHEATHS	SUBSEQUENT REPORT OF BEING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF BEING CASING OR REPAIR
NOTICE OF INTENTION TO SHUT OR ABANDON WELL	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ABANDON CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECKING IN THE NATURE OF REPORT, NOTED BY STATE)

Well No. _____ is located _____ ft. from _____ line and _____ ft. from _____ line of sec. _____
 (Township) (Range) (Section) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show new weights and lengths of proposed casing; indicate, including jobs, cementing points, and all other important proposed work)

I understand that this plan of work and its results apply to the well described above and that I agree to submit the required reports and summaries to the Bureau of Land Management, Department of the Interior, Washington, D. C. 20507.

Company _____
 Address _____

