

1980-1981 No. 46 1988-
1989 No. 46

Santa Fe

卷之三

23 - 078194

卷之三

REPORTS ON WELLS

RECOMMENDED REPORT OF WATER SHOTGUN
RECOMMENDED REPORT OF SHOTGUN OR ARIZING
RECOMMENDED REPORT OF ABANDONED CARDS
RECOMMENDED REPORT OF REPAIRING OR REPAIR
RECOMMENDED REPORT OF ABANDONMENT
SUPPLEMENTARY WELL HISTORY

三

1960

Java-Script

Well No. 1 is located 45 ft. from the line and 350 ft. from the line of sec.

B. A. 1/4 Sec. 19

T-50-N **T-14-N**
TWO 1 THREE 1

卷之三

Undes. Dakota

Ban Jura

New Mexico (State or Territory)

The elevation of the ~~1000 feet~~ above sea level is **5340** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Well spudded 5/20/60.
Drilled 13-3/4" hole to 198' set 10-3/4" casing at 195' cemented W/300 gal. Casing was pressured to 500# for 30 Min. with no loss in pressure. After cement set plug was drilled and run on B. O. P. closed and casing pressured 500# for 30 Min. with no appreciable drop in pressure. Drilling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Delhi-Taylor Oil Corporation

Address P. O. Box 1178

Farmington, New Mexico

By J. B. Howell
Title Dist. Dept.