

Abstract

NEW (SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency _____

Allottee

² **Lease No.**

SUNDRY NOTICES AND REPORTS ON WELLS

RECEIVED
WELLS

SEP 4 1958

| | |
|---|--|
| NOTICE OF INTENTION TO DRILL | SUBSEQUENT REPORT OF WATER SHUT-OFF |
| NOTICE OF INTENTION TO CHANGE PLANS | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF | SUBSEQUENT REPORT OF ALTERING CASING |
| NOTICE OF INTENTION TO REDRILL OR REPAIR WELL | SUBSEQUENT REPORT OF REDRILLING OR REPAIR |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE | SUBSEQUENT REPORT OF ABANDONMENT |
| NOTICE OF INTENTION TO PULL OR ALTER CASING | SUPPLEMENTARY WELL HISTORY |
| NOTICE OF INTENTION TO ABANDON WELL | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

[REDACTED]

19. ~~_____~~

Well No. 1 is located 100 ft. from N line and 100 ft. from E line of sec. 1

(1/4 Sec. and Sec. No.)

($\frac{1}{4}$ Sec. and Sec. No.)

(Twp.)

(Twp.)

(Range)

(Range)

(Merit)

(Meridian)

Abstract

(Field)

(County or Subdivision)

The elevation of the ~~center floor~~ above sea level is 222.7 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

This work was planned as per Notice of Intention to Abandon w/10 on of amount from 2000' to 2004', 20 on from 1990-1999' and 20 on w/10y hole number in the top of the surface pipe. The job was supervised by Mr. Stanley Branch at the direction of Mr. Richard King.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company

Page 21 Summary

Address

Walt H. Rostow & Associates, Inc.

200 2. Summary

Peru: Peru

Original signed by T. A. Dugan

By

Customer Taking Responsibility

Title