1		
1		
	i	 
1		
	<del> </del>	 
	!	•

## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office	Santa Fe
Lease No	077754
Unit g	chamcher

SUNDRY NOTICES AND REPORTS ON WELLS IVE

SUNDRY	NOTICES A	ND REPOR	IS ON WE	E SEIVE
NOTICE OF INTENTION TO DRILL.		SUBSEQUENT REPO	RT OF WATER SHUT-OFF.	3.1
NOTICE OF INTENTION TO CHANGE	PLANS	11	RT OF SHOOTING OR ACI	DIZING.
NOTICE OF INTENTION TO TEST WA	TER SHUT-OFF	SUBSEQUENT REPO	RT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL	OR REPAIR WELL	SUBSEQUENT REPO	RT OF RE-DRILLING OR F	REPAREDLOGICAL D' IN
NOTICE OF INTENTION TO SHOOT O	R ACIDIZE	SUBSEQUENT REPO	RT OF ABANDONMENT	THE WELL WITH
NOTICE OF INTENTION TO PULL OR	ALTER CASING	SUPPLEMENTARY W	WELL HISTORY	
NOTICE OF INTENTION TO ABANDO	• WELL		<b></b>	<b>x</b>
(INDIC	ATE ABOVE BY CHECK MARK N	IATURE OF REPORT, NOT	ICE, OR OTHER DATA)	
		Age1	1 14	, 19. <b>51</b>
Well No. 11 is loca	ated 1650 ft. from	S line and	ft. from	line of sec. 13
W. Section 10 (% Sec. and Sec. No.)	(Twp.) (i	late Lange)	(Meridian)	
Dasin Dakota	San Aven		lzek veli	
(Field)	(County or	Subdivision)	(State or T	erritory)
The elevation of the derric		s of work		
(State names of and expected depths	to objective sands; show sizes		of proposed casings; indic	ate mudding jobs, cement
4-9-51 Total Depth Water fractured Dake 7245-52;7270-75 with Breakdown pressur Injection rate 50 BF contained 15 calcium Pressured up on cast BDA. Ran correlation 25,000% send in.	ta perforated in 52,626 gallous e 1700%, max pr M. Flush 10,122 chloride & 1 ga	tervals 71.94- pater and 50,4 2900%, avg tr gallons. Fra 1 W-27/1000 g ore part & sp	000% sand. pr 2700-2050% c water al. stied 250 gal d 5 balls afte	RECEIVED APR1 9 1961
I understand that this plan of wo		rriting by the Geologics	al Survey before operation	ns may be commenced
Company The Company	ural Cas Company			
Address Box 990, Pe	relagion, No Pe	<b>x</b> lco	Odgatal Gigned D	W. Machan
		Ву		
		Title	Petroleum En	rineer