UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT RECEIVED

nd Reports on Wells	h 2: 2 2		/
		5.	Lease Number SF-077764
070 FARIGING	IOIA' (AIM	6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
COMPANY			
		8.	Well Name & Number Schumacher #10
9 (505) 326-9700		9.	API Well No. 30-045-09547
Location of Well, Footage, Sec., T, R, M 1090'FNL 800'FEL, Sec.18, T-30-N, R-10-W, NMPM	10.	Field and Pool Blanco Mesaverde	
	11.	County and State San Juan Co, NM	
NATURE OF NOTICE,	REPORT,	OTHER	DATA
Recompletion Plugging Back Casing Repair Altering Casing	New Con Non-Rou Water S Convers	struc tine hut o	tion Fracturing ff
Operations SDON. FOOH w/2-3/8" tbg. T 535'. ND BOP. NU WH.	TH W/182 RD. Rig	: jts ; rele	2-3/8″ 4.7# ased.
SDON. TOOH w/2-3/8" tbg. T	TH w/182 RD. Rig	: jts , rele	2-3/8" 4.7# ased.
SDON. TOOH w/2-3/8" tbg. T	TH w/182 RD. Rig	; jts g rele	2-3/8" 4.7# ased. AUG 0 6 1999
SDON. TOOH w/2-3/8" tbg. T	TH w/182 RD. Rig	, rele	ased.
SDON. TOOH w/2-3/8" tbg. T 535'. ND BOP. NU WH.	RD. Rig	, rele	AUG O G 1999 OUL COM, DIV.
SDON. TOOH w/2-3/8" tbg. T	RD. Rig	y rele	AUG O 6 1999 OIL COM. DIV. DIV.
	O70 FARMING COMPANY 9 (505) 326-9700 7, R, M R-10-W, NMPM NATURE OF NOTICE, 1 Type of Action Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other - tubing repa	O70 FARMINGTON, NM COMPANY 9 (505) 326-9700 7, R, M R-10-W, NMPM NATURE OF NOTICE, REPORT, Type of Action Abandonment Change Recompletion New Con Plugging Back Non-Rou Casing Repair Water S Altering Casing Convers Other - tubing repair	99 JUL 6 Ph 2: 22 5. 070 FARMINGTON, NM 6. 7. COMPANY 8. 9 (505) 326-9700 9. 7, R, M R-10-W, NMPM 11. NATURE OF NOTICE, REPORT, OTHER Type of Action Abandonment Change of Planta Conversion to Other - tubing repair Other - tubing repair