

(SUBMIT IN TRIPLICATE)

Indian Agency Nava jo

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Allottee Humble O & R

Lease No. 14-20-603-1252

	10	
		X

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	XX
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 10, 1963

Well No. Hartley-Nava jo #2 is located 360 ft. from [N] line and 2125 ft. from [E] line of sec. 10

SW 1/4 Sec. 10 30 N 18 W NMPM
(34 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Wildcat San Juan New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4891 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs; cementing points, and all other important proposed work)

Plug and abandon

Cement Plugs set at: 937' to 987' - 11 sks. reg. cmt.
275' to 375' - 32 sks. reg. cmt.
0 to 15' - 7 sks. reg. cmt.

4' surface marker.

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO



I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Leora O. Shaw

Address 1007 West Apache St.

Farmington, New Mexico

By Lee W. Kilgore
Lee W. Kilgore
Title Agent

