



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Santa Fe
Lease No. ST-080362-C
Unit L

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	<input checked="" type="checkbox"/>	Subsequent Report of Sand-Oil Free	<input checked="" type="checkbox"/>

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

NORTH WATERFLOW UNIT

Farmington, New Mexico July 14, 1958

Well No. 2 is located 1900 ft. from N line and 990 ft. from W line of sec. 10

2 1/4 of Section 10

T-30-N

R-15-W

(1/4 Sec. and Sec. No.)

(Twp.)

(Range)

(Meridian)

Wilcox

San Juan

New Mexico

(Field)

(County or Subdivision)

(State or Territory)

The elevation of the derrick floor above sea level is 5336 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

7-2-58 Sand-Oil fraced Gallup formation in open hole from 4563' - 4476' with 30,000 gallons lease crude and 25,000 sand. Swabbed 11 days, failed to recover load oil. 97 barrels left in formation.

7-14-58 Plan to plug and abandon well as follows:
Cement from bottom of open hole back into 7" casing to at least 4050'.
Set cast iron bridge plug over top of cement.
Run free point indicator and cut and recover casing at free point.
Set 100' cement plug 30' inside casing stub and 50' outside casing stub.
Set other cement plugs as indicated from amount of hole left open.
Set cement plug in top of surface casing and install abandonment marker.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Humble Oil & Refining Company

Address Box 1268

Farmington, New Mexico

By

Russell M. Lilly
Russell M. Lilly

Title

District Superintendent