

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other X - Injection
-
2. NAME OF OPERATOR ARCO Oil & Gas Co., Div. of
Atlantic Richfield Company
-
3. ADDRESS OF OPERATOR 707-17th Street,
P.O. Box 5540, Denver, CO 80217
-
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17
below.) Unit "B"
AT SURFACE: 350' FNL & 1670' FEL, Sec. 9
AT TOP PROD. INTERVAL: Appx. same
AT TOTAL DEPTH: Appx. same
-
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,
REPORT, OR OTHER DATA

5. LEASE
S.F. 081226-B
-
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
USA
-
7. UNIT AGREEMENT NAME
Horseshoe Gallup Unit
-
8. FARM OR LEASE NAME
Horseshoe Gallup Unit
-
9. WELL NO.
263
-
10. FIELD OR WILDCAT NAME
Horseshoe Gallup ~~Unit~~
-
11. SEC., T., R., M., OR BLK. AND SURVEY OR
AREA
Sec. 9-30N-16W
-
12. COUNTY OR PARISH: 13. STATE
San Juan New Mexico
-
14. API NO.
None Assigned
-
15. ELEVATIONS (SHOW DF, KOB, AND WD)
5702' GR

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*
(other)

RECEIVED
RECEIVED
(NOTE: Report results of multiple comparisons for
change (Form 9-330.)
JAN 06 1984
OIL CON. DIV.
DIST. 3
BUREAU OF LAND MANAGEMENT
FARMING IN THE WEST

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*
- ARCO has plugged and abandoned the subject well in accordance with the Sundry Notice dated December 30, 1982, and approved by the BLM-MMS on January 11, 1983. Injection interval 1485' - 1535', Gallup fm. Spotted cement plugs as per the attached plugging operations report.

Completed P & A, 8-30-83.

Final restoration will be commenced as soon as weather permits. An additional subsequent report will be filed when restoration has been completed.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Stephen Rose TITLE Dist. Prod. Supt. DATE November 30, 1983
S. C. Rose

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL IF ANY: _____

NM1055

HSG #263, Horseshoe Gallup Field

P & A OPERATIONS:

MI RU 8/26/83. Pmpd 20 sx cmt plug thru tbg. SI & WOC.

Backed off @ safety jt & POH wet. Had 3 jts of tbg cmt. Perf'd 4 holes @ 1335', sptd 30 sx cmt & sqz'd 20 sx thru perfs.

FINAL REPORT - WELL P & A 8/30/83.]

Perf'd 2 holes @ 128', pmpd 30 sx cmt leaving csg full of cmt. Cut wellhd off & instl'd DH marker.